

TRON UPRIGHT CABINET PAPER SET

(1) off white card stock

STAPLE
HERE

STAPLE
HERE

No. _____

NAME _____

CLOCK NO. _____

DATE _____

REMARKS _____

(2) off white card stock

TRON OPTION SWITCH SETTINGS

SWITCH NO. 1 - AT B 3 - LOCATED ON SOUND I/O P.C. BOARD

	SW #1	SW #2	SW #3	SW #4	SW #5	SW #6	SW #7	SW#8	SW#9	SW #10
2 COIN METERS	ON		NOT USED	NOT USED	NOT USED	NOT USED	NOT USED	NOT USED	NOT USED	NOT USED
1 COIN METER	OFF									
MINI/UPRIGHT COCKTAIL TABLE		ON								
BUY IN ALLOWED			ON							
NO BUY IN			OFF							
FREEZE VIDEO										ON
NORMAL OPERATION										OFF

(3) off white card stock

O. K.


FOR SHIPMENT

By _____

M051-0031-0000

SWITCH NO. 3 - AT D 14 - LOCATED ON SOUND I/O P.C. BOARD

	SW #1	**SW #2	**SW #3	**SW #4
NORMAL OPERATION	OFF			
SOUND I/O DIAGNOSTIC MODE	ON			
NORMAL OPERATION		OFF		
RAM/ROM TEST		ON		
INDICATES TEST RESULTS VIA YELLOW L E D ON SOUND I/O BOARD: FAST FLASH = BAD ROM SLOW FLASH = BAD RAM				
NORMAL OPERATION			OFF	
OSCILLATOR TEST			ON	
NORMAL OPERATION				OFF
FILTER TEST				ON



****NO EFFECT IF SW#1 OF SWITCH NO. 3 IS IN THE "OFF" POSITION.**

The remainder of Tron's most common option settings are conducted during the machine setup period of the self-test mode. Simply follow the on-screen instructions to make any adjustments you feel are necessary.
M051-00628-A011

(5) off white paper

THIS EQUIPMENT HAS NOT BEEN TESTED TO SHOW COMPLIANCE WITH NEW FCC RULES (47 CFR PART 15) DESIGNED TO LIMIT INTERFERENCE TO RADIO AND TV RECEPTION. OPERATION OF THIS EQUIPMENT IN A RESIDENTIAL AREA IS LIKELY TO CAUSE UNACCEPTABLE INTERFERENCE TO RADIO COMMUNICATION REQUIRING THE OPERATOR TO TAKE WHATEVER STEPS ARE NECESSARY TO CORRECT THE INTERFERENCE.


(4) off white paper

COUNTRY OF ORIGIN
U.S.A.
M051-00111-A001

(coin door controls) white paper

VOLUME CONTROL POT
M051-121-A001

TEST CREDIT BUTTON



(6) off white card stock

CABINET

TRON-UR No

(7) white paper

WARNING: ELECTRONIC DEVICES ON THIS UNIT MAY BE DESTROYED WHEN SUBJECTED TO ELECTROSTATIC CHARGES. PERSONNEL AND TOOLS MUST BE PROPERLY GROUNDED WHEN HANDLING.